



VEHICLE CONDITION REPORT

2006 Hummer H3

Our condition reports are for the benefit of our customers. At McLachlan Automotive we recondition our vehicles to specific standards

LEGEND

N = Normal for year and mileage
 D = Attention required (see notes at bottom of page)
 N/A = Not applicable

ELECTRICAL

Alternator	N
Accessories	N
Lighting	N

COOLING / HEATING SYSTEM

Coolant strength	N
System mechanical condition	N

POWERTRAIN

Engine	N
Transmission	N/A
Differential (s)	N/A
Transfer case	N/A

SUSPENSION

Linkages	N
Steering gear (box)	N

EXHAUST

Exhaust condition	N
-------------------	---

TIRES

Left front tire: % remaining	60%
Right front tire: % remaining	60%
Left rear tire: % remaining	50%
Right rear tire: % remaining	50%

BRAKES

Hydraulic system	N
Front brake remaining	99%
Rear brakes remaining	99%

SPECIAL NOTES: