



## VEHICLE CONDITION REPORT

**2007 CHEVROLET AVALANCH LHL17728**

Our condition reports are for the benefit of our customers.  
At McLachlan Automotive we recondition our vehicles to specific standards

### LEGEND

N = Normal for year and mileage  
D = Attention required (see notes at bottom of page)  
N/A = Not applicable

ELECTRICAL	Alternator	N
	Accessories	N
	Lighting	N

COOLING / HEATING SYSTEM	Coolant strength	N
	System mechanical condition	N

POWERTRAIN	Engine	N
	Transmission	N
	Differential (s)	N
	Transfer case	N

SUSPENSION	Linkages	N
	Steering gear (box)	N

EXHAUST	Exhaust condition	N
---------	-------------------	---

TIRES	Left front tire: % remaining	55%
	Right front tire: % remaining	55%
	Left rear tire: % remaining	55%
	Right rear tire: % remaining	55%

BRAKES	Hydraulic system	N
	Front brake remaining	70%
	Rear brakes remaining	70%

### SPECIAL NOTES:

Mechanical Condition: Excellent  
Body condition: Excellent

Fresh oil change  
Rear brakes serviced