



## VEHICLE CONDITION REPORT

**07 GMC Sierra 79887**

Our condition reports are for the benefit of our customers. At McLachlan Automotive we recondition our vehicles to specific standards

### LEGEND

N = Normal for year and mileage  
D = Attention required (see notes at bottom of page)  
N/A = Not applicable

#### ELECTRICAL

Alternator	N
Accessories	N
Lighting	N

#### COOLING / HEATING SYSTEM

Coolant strength	N
System mechanical condition	N

#### POWERTRAIN

Engine	N
Transmission	N/A
Differential (s)	N/A
Transfer case	N/A

#### SUSPENSION

Linkages	N
Steering gear (box)	N

#### EXHAUST

Exhaust condition	N
-------------------	---

#### TIRES

Left front tire: % remaining	50%
Right front tire: % remaining	50%
Left rear tire: % remaining	50%
Right rear tire: % remaining	50%

#### BRAKES

Hydraulic system	N
Front brake remaining	35%
Rear brakes remaining	50%

SPECIAL NOTES: